



# Service Bulletin No. 1055

<b>COACH MODEL</b>	: C2000 Series
<b>BULLETIN TYPE</b>	: Service information
<b>MANUAL &amp; SECTION</b>	: N/A
<b>DATE</b>	: November 30th, 2000
<b>SUBJECT</b>	: Introduction of Maintenance Manual M501
<b>TERMS &amp; CONDITIONS</b>	: Note that no claims will be accepted with reference to this Bulletin.

## **DESCRIPTION:**

Maintenance Manual M501 has been released for distribution to end-users. It is applicable to C2045 coaches as from units #45137 (Cummins engine) and #45621 (Detroit Diesel engine), on which Lucas D-ELSA disc brakes have been introduced on the front, drive, and tag axle.

Technicians servicing C2045 coaches equipped with D3 disc brakes on front and tag axle should keep referring to Maintenance Manual M457, revision A.

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.

K:\SERVICE\USA\CDROM\SB1055.JA

**THIS PAGE HAS BEEN LEFT BLANK INTENTIONALLY**