

## Service Bulletin No. 1074

COACH MODEL : C2000 Series

**BULLETIN TYPE**: Service information

MANUAL & SECTION : Spare Parts Manual : Section 6212 - Air intake system

DATE : January 31st, 2001

**SUBJECT**: Intercooler to inlet manifold piping

**TERMS & CONDITIONS**: Parts may be purchased from your nearest International Coach Parts Inc. dealer. No claims will be accepted with reference to this Bulletin.

## **DESCRIPTION:**

Commuter Spare Parts Manual #S1190 shows an error on page #621209-2118. The actual vehicles are fitted with a single silicone hose.

To update your copy of Spare Parts Manual #S1190, replace old page #621209-2118 by the new page attached to this Bulletin.

Spare Parts Manual #S1190, revision A, has been updated and will not require this change.

## PARTS:

Always use genuine maintenance products and parts. Do not accept imitations.

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.

K:\SERVICEB\USA\PmSB#\SB1074



DATE: JAN 31<sup>ST</sup>, 2001 **SERVICE BULLETIN No. 1074** PAGE 2/2



