

ADDRESSEES	: ABC Customer Care and Parts Source
DATE	: December 06th, 2018
SUBJECT OF BULLETIN	: To install new transmission oil dipstick on CX35 with Cummins L9 engine

SB1504 is applicable to following units:

Model	VIN	Number of vehicles
CX35 with ISL9 engine	48775,	4
	49270 → 49329	60
	49640 → 49709	70
	49711 → 49735	25
CX35 with L9 engine	49787 → 49804	18
	49807 → 49808	2
	49810 → 49813	4
	49815	1
	49817 → 49836	20
	49838 → 49840	3
	49861 → 49863	3
	49866 → 49867	2
	49872	1
49874 → 49875	2	
Total: 56		

Remark: PK74639 contains vehicles with Cummins ISL9 as well as L9 engines, nevertheless only L9 vehicles are affected. Service bulletin number changed from "SB1504" to "SB1504A" and distributed through the portal on 2018-12-06.

Following units already changed in the field on 2018-12-06

Claim information from WVR, dd 2018-09-19

Model	VIN	Number of vehicles
CX35 with L9 engine	49710, 49809, 49837	3
	49841 → 49860	20
	49864	1
	49868 → 49871	4
	49877	1
Total: 29		

+

Claim information from WV, dd 2018-12-06

Model	VIN	Number of vehicles
CX35 with L9 engine	49805 → 49806	2
	49814, 49816	2
	49865, 49873, 49878	3
Total: 7		

List of vehicles based on PK74639/PK75204