



Service Bulletin No. 1053

MODEL : All

TYPE : Service information

MANUAL &

SECTION : Maintenance Manual : Chapter 4 - Axles, wheels, and tires

DATE : August 31st, 2000

SUBJECT : Balancing brake drums and hub centered wheels

CONDITIONS : Service information only. Note that no claims will be accepted with reference to this Bulletin.

DESCRIPTION:

In order to properly balance brake drums, or steel or alloy wheel and tire assemblies, it is necessary to center them by the bore, and not by the stud holes (see Figures 1 and 2).



F05167



F05168

Figures 1 and 2 : Wheel and tire assembly installed on a balancer, and centered by the bore.

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.

K:\SERVICE\USA\PmSB\SB1053LDW

THIS PAGE HAS BEEN LEFT BLANK INTENTIONALLY

K:\SERVICE\USA\PM\SB#SB1053LDW