

ECH TIP

#1210

All VanHool Models **COACH MODEL:**

7/20/12 DATE:

Shock absorber information and inspection SUBJECT:

Inspection Guide

Extend shock fully and look for the following

Shock is Misting

Road Grime

Shock is Leaking







An even coating of oil is present on shock body.

SHOCK IS OK

Mud mixed with oil caked on exterior of shock. Evidence of Misting present.

SHOCK IS OK

Oil is leaking above road grime area. Drops of oil present on shock REPLACE SHOCK

OTHER CONCERNS

- Attachments broken
- Shock will not adjust

REPLACE SHOCK

VEHICLE RIDING SOFT? ADJUST FIRST!

- 1.Remove shock and compress fully until you feel the adjuster engage (See figure 1).
- 2. Make sure the shock is in unadjusted position by turning counter clockwise while counting 1/2 turns.
- 3.To increase the rebound damping, turn the piston rod clockwise up to 2 1/2 turns (See figure 2)

