


COACH MODEL : C2045, T2145
DATE : 27 Sep 2021
SUBJECT : Water leaking in Luggage bays right side



If the water is leaking into the luggage bay you will need to remove the wheel well cover and check to see if the channel in the top front corner of wheel well as shown in this picture is open with no sealer.

To repair the problem inject sealer into the channel, making sure to fill in the area.