

COACH MODEL : Van Hool Coach
DATE : 3/16/2020
SUBJECT : Kiddie Fire Suppression



Kiddie Fire Suppression may deploy accidentally if the Tamper seal is missing. During inspections by operators and technicians if the Tamper seal is missing it is recommended that it be replaced. Replacing can minimize the chance of accidental deployment of the Kiddie Fire Suppressant system.

The Tamper seal part number is ABC-10315 and can be ordered from ABC Parts Source.



#ABC-10315

Seal, Tamper Replacement - For

