

COACH MODEL : C,CX,T,TX

DATE : 3/20/2014

SUBJECT : NEW DEFROSTER BLOWER MOTOR

There is a new style defroster motor designed to replace existing units, the only difference is the heat sink incorporated on the new motor assembly. This is a direct replacement assembly, no modifications to the wiring will be necessary.

Driver's Defroster Fan Update

OLD P/N 10947040

NEW P/N 11370295

