



# SERVICE BULLETIN No.1105

Circulate to listed addressees

|                               |   |
|-------------------------------|---|
| <b>COACH MODEL</b>            | : T2145, S2145 and C2045  |
| <b>BULLETIN TYPE</b>          | : Service Information   |
| <b>MANUAL &amp; SECTION</b>   | : Maintenance Manual: Chapter 9 – Electrical system<br>Spare Parts Manual: Section 783009 - Dashboard |
| <b>PARTS BOOK REVISION</b>    | : Yes   |
| <b>DATE</b>                   | : March 22nd, 2002  |
| <b>SUBJECT</b>                | : <b>Hazard warning flasher switch</b>  |
| <b>TERMS &amp; CONDITIONS</b> | : No claims will be accepted with reference to this Bulletin.   |

## APPLICATION:

The product change subject of this Bulletin has been cut into production as from following units:

| Model | Engine         | VIN   |
|-------|----------------|-------|
| T2145 | Cummins        | 44268 |
|       | Detroit Diesel | 44585 |
| C2045 | Cummins        | 45373 |
|       | Detroit Diesel | 45829 |
| S2145 | N/A            | 42226 |

## DESCRIPTION:

In an effort to enhance driver comfort and safety, the hazard warning flasher electrical circuit has been rewired. As of the units mentioned under "Application," the dash mounted hazard warning flasher switch will illuminate when the exterior lighting is being switched on, improving the visibility of the switch.

The button will glow faintly in the dark when the hazard warning flasher is not in use. It will flash in a normal fashion with the flasher activated.

*Service personnel: please read, initial and circulate.*

| Service Manager | Parts Manager | Warranty Administrator | Workshop Foreman | Service Technician |
|-----------------|---------------|------------------------|------------------|--------------------|
|                 |               |                        |                  |                    |

## **PARTS:**

### **Old parts**

| <b>Part No.</b> | <b>Description</b>            | <b>Qty.</b> |
|-----------------|-------------------------------|-------------|
| VH 660761405    | Hazard warning flasher switch | 1           |
| VH 660768602    | Plug                          | 1           |

### **New parts**

| <b>Part No.</b> | <b>Description</b>            | <b>Qty.</b> |
|-----------------|-------------------------------|-------------|
| VH 10753354     | Hazard warning flasher switch | 1           |
| VH 10753357     | Plug                          | 1           |

- Old and new parts are not interchangeable. Installation of switch VH 10753354 requires minor modifications of the dash circuitry.
- Both old and new parts will be available as service replacements.
- Parts may be purchased from your nearest International ABC Companies Parts Source dealer.
- Always use genuine maintenance products and parts. Do not accept imitations.
- Parts disposition: discard according to applicable environmental regulations.

## **SERVICE INFORMATION:**

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.