



VEHICLE LIST FOR

SERVICE BULLETIN SB1504

| | |
|----------------------------|--|
| ADDRESSEES | : ABC Customer Care and Parts Source |
| DATE | : September 19th, 2018 |
| SUBJECT OF BULLETIN | : To install new transmission oil dipstick on CX35 |

SB1504 is applicable to following units:

| Model | VIN | Number of vehicles |
|--------------|-------------------|---------------------------|
| CX35 | 48775, | 1 |
| | 49270 → 49329 | 60 |
| | 49640 → 49735 | 96 |
| | 49787 → 49866 | 80 |
| | 49868 → 49875 | 8 |
| | 49877 | 1 |
| | Total: 246 | |

List of vehicles based on PK74639/PK75204