

COMPANIES



- (Contact Limitation & Eradication of Airborne Noxious Systems)
- 3 layers of passenger and driver protection
- Includes new & pre-owned coach and service offers



ABC "CLEANS" Products & Services





Interior sanitization/disinfection



HVAC purification systems



Contact partitions & passenger hygiene



Interior sanitization/disinfection




Electrostatic fogging of coach interior



- 99.994% Reduction in Virus Control including the Human Coronavirus
- EPA approved water soluble disinfectant also used in commercial airlines
- Solution is electrically charged allowing uniform coating and "wraparound" distribution on surfaces
- Services conducted by ABC on site or at customer location

Available: May/June

Cost: 45' / 35' / Double Deck








Upgraded cabin filter system, MERV 13 (new and retro)

- Reduces cabin particulates by 90% between 1 and 5 microns and smaller
- Can be installed in existing systems

Cost: \$260 (to be replaced every 3 months)

Available: 4-6 week delivery









Factory HEPA filtration

Captures 99.9% of Particles (bacteria, fungi and larger viruses or virus clumps)

Cost: Priced per coach configuration at

time of sale

Available: Factory order









UV light HVAC disinfection system (new and retro)

- Eliminates 90% of microbial contaminants after 10 minutes of exposure and 99% after 1 hour
- Reduces maintenance of HVAC system components
- Can be installed in existing systems



taken and prioritized)




| Microorganism | Single Pass | | |
|-------------------|-------------|---------|-------------|
| | Minimum | Average | LOG Average |
| Coronavirus | 78.33% | 97.55% | 1 |
| Tuberculosis | 57.88% | 87.72% | 0 |
| Influenza A virus | 38.21% | 68.89% | 0 |
| Smallpox | 46.19% | 77.76% | 0 |




















Coil after UV light application

Simplified Maintenance

When UV-C lights are properly installed they can eliminate the need for coil and drain pan cleaning. Maintenance personnel are no longer exposed to disinfectants and other cleaning chemicals required for these tasks. Use of UV-C lights can result in a 99 percent reduction of the concentration of germs on irradiated surfaces within the A/C system

Advanced Power Supply

Our 24-30 VDC power supply utilizes a high frequency electronic ballast design for stable lamp operation and increased lamp life. The power supply is compact and easily mounts in the tight confines of the A/C

Teflon® Coated, Water-Resistant Lamps

The UV lamps are safety-coated with a Teffon® sleeve. They are water-resistant for mounting in wet locations such as the coil and drain pan. These TUVC-246 UV-C lamps incorporate a durable shielded design that provides longer lamp life in all conditions.



Contact Partitions & Passenger Hygiene



Driver protection

Enclosure

- Full driver enclosure
- Transparent
- Easily cleaned

Cost: per coach model

Available: for order







Contact Partitions & Passenger Hygiene



Driver protection

Partition

- Permanent barrier
- Easy cleaning
- Transparent

Cost: In dev

Available: TBD







Contact Partitions & Passenger Hygiene






- Clear plastic barrier
- Easy disinfecting and cleaning
- Snaps into position for easy installation and removal

Cost: \$29.95

Available: Orders being taken now









Contact partitions & passenger hygiene



<u>Passenger Protection</u>



- Clear plastic barrier
- Easy disinfecting and cleaning
- Snaps into position for easy installation and removal

Cost: \$29.95 per 2 seat section

Available: Orders being taken now








Contact partitions & passenger hygiene



<u>Passenger Protection</u>

Removable protective shield







Ceiling Mounted Snaps



Reclined

Contact partitions & passenger hygiene



<u>Passenger Protection</u>

Partition

- Permanent barrier
- Easy cleaning
- Transparent

Cost: In development

Available: In development

Hand sanitizer stations

Can be installed at multiple locations throughout coach

Cost: \$55 (Base + 6 bottles)

Available: OUT OF STOCK – Shipment in transit









CLEANS support/marketing materials









This Vehicle Has Been Electrostatically Sanitized For Your Safety

Date:

Technician:

