

COACH MODEL : 2020 Van Hool Coach

DATE : 3/16/2020

SUBJECT :  Eberspächer New Diagnostic Cable



The new 2020 Van Hool coaches upgraded the harness for the pre-heater. With this change a new diagnostic harness will be needed to use the EDITH software to perform diagnostics on the pre-heater. Part number for this new cable is **11701738** (Cable, Diagnostic Connector), and is available through ABC Parts Source. (Figure 1) The new cable will do away with the round cable interlink used in prior years. The new diagnostic cable (11701738) will only be used on 2020 and newer Van Hool coaches.

For prior to the 2020 model ABC-14452 diagnostic cable will still be needed for pre-heater diagnostics. (Figure 2) The Eberspächer diagnostic tools are compatible for either diagnostic harness, only the diagnostic cable has changed. (Figure 3 and 3.1)




Figure 1 Part # 11701738 (For 2020 Van Hools)



Figure 2 Part # ABC-14452 (For prior to 2020 Van Hools)



Figure 3 Part #ABC-13033



Figure 3.1 Part #ABC-15072