



Service Bulletin No. 1047

MODEL : T2100 Series

TYPE : Service information

**MANUAL &
SECTION** : N/A

DATE : June 30th, 2000

SUBJECT : Introduction of Maintenance Manual M494

CONDITIONS : Service information only. Note that no claims will be accepted with reference to this Bulletin.

DESCRIPTION:

Maintenance Manual M494 has been released for distribution to end-users. It is applicable to T2100 coaches as from units #44055 (Cummins engine) and #43945 (Detroit Diesel engine), on which the new D-ELSA disc brakes on the front, drive, and tag axle have been introduced.

Technicians servicing T2100 coaches equipped with D3 disc brakes on front and tag axle should keep referring to Maintenance Manual M380, version D.

Service Bulletins are issued to supplement or supersede information in the Van Hool manuals. Note Service Bulletin number, date and subject on the register at the end of the relevant chapter(s). File Service Bulletin separately for future reference.

K:\SERVICE\USA\CDROM\SB1047JA

THIS PAGE HAS BEEN LEFT BLANK INTENTIONALLY